



# NMSU Fire Department



## 2012 Annual Fire Safety Report

### Clery Act Requirement

New Mexico State University

Fire Safety Reporting [18] HEOA

Reporting Date January 1, 2012 to December 31, 2012

---

*NOTE: All fire drills reported below are supervised and have mandatory evacuation for all individuals. During the fire drills there is an inspection of: audio sound, synchronization of light strobes, exit doors, and other factors of the system in place.*

---

#### **I. On-campus student housing facilities, description of the facilities and description of fire safety system.**

##### **Residence Halls**

###### **Garcia Hall**

Garcia Hall is a three story fire resistive building with four patios. Dorm rooms encircle the patios.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system.

Fire Drill: 1 on 08/28/2012

One fire reported, information on [II Fire Statistics](#).



# NMSU Fire Department



## **Monagle Hall**

Monagle Hall is three story fire resistive building with three patios. Dorm rooms encircle the patios.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center.

Fire Drill: 1 on 08/28/2012

## **Piñon Hall**

Piñon Hall is a three story wood frame structure. The building is two separate sections connected by a common area.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system.

Fire Drill: 1 on 08/29/2012

## **Rhodes Garrett Hamiel (RGH)**

RGH is a three story fire resistive building with traditional dorm rooms off the main hallway.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. Hallways and corridors are protected by with an automatic wet pipe sprinkler system.

Fire Drill: 1 on 08/28/2012



# NMSU Fire Department



## Campus Apartments

### Cervantes Village

Cervantes Village are multiple single story wood frame buildings, they contain one, two, and four bedroom apartments.

Fire Protection: The rooms contain individual smoke detectors and CO alarm detectors.

One fire reported, information on [II Fire Statistics](#).

### Chamisa Village I & II

Chamisa Village is a complex made-up of three story wood frame buildings. Apartments come in two and four bedroom layouts.

Fire Protection: Apartments contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system.

Fire Drills: 1 on 09/05/2012

### Vista Del Monte

Vista Del Monte is a complex made up of two story wood frame buildings. Apartments are in two-bedroom configuration.

Fire Protection: Apartments contain individual smoke detectors and CO detectors.

## Family Housing

### Tom Fort and Sutherland Villages

Tom Fort and Sutherland are single-family, single story fire resistive homes.

Fire Protection: The homes contain individual smoke detectors and CO detectors.



# NMSU Fire Department



## **Cole Village**

Cole Village are two story fire resistive town houses, they are two bedrooms configuration.

Fire Protection: Each home contains individual smoke detectors and CO detectors.

## **Greek Housing**

### **Greek & ROTC West (buildings 100-400)**

Greek Complex West is made up of four sections. They are single story fire resistive dormitory buildings.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations are monitored by a fire alarm system. It reports directly to our dispatch center.

Fire Drill at Greek 100: 1 on 09/04/2012

Fire Drill at Greek 200: 1 on 09/04/2012

Fire Drill at Greek 300: 1 on 09/04/2012

Fire Drill at Greek 400: 1 on 09/04/2012

### **Greek Complex East (buildings 500-800)**

Greek Complex East is made up of four, two story wood frame building, each section contains four bedrooms.

Fire Protection: Pull stations and smoke detectors in the hallways, they are monitored by a fire alarm system. The system reports directly to our dispatch center. Each individual bedroom has a smoke detector in place; they are not on the fire alarm reporting system.

Fire Drill at Greek 500: 1 on 09/04/2012

Fire Drill at Greek 600: 1 on 09/04/2012

Fire Drill at Greek 700: 1 on 09/04/2012

Fire Drill at Greek 800: 1 on 09/04/2012



# NMSU Fire Department



## **CHI OMEGA**

CHI OMEGA is a residential sorority, two story wood frame home.

Fire Protection: Bedrooms contain individual smoke detectors. Smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. A fire sprinkler system is currently under construction and review at Chi Omega.

Fire Drill: 1 on 08/29/2012

One fire reported, information on [II Fire Statistics](#).

## **DELTA ZETA**

DELTA ZETA is a residential sorority, single story wood frame home.

Dorm rooms contain individual smoke detectors. Smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatched center.

Fire Drill: 1 on 08/29/2012

## **ZETA TAU ALPHA**

ZETA TAU ALPHA is a residential sorority, two story wood frame home.

Fire Protection: Smoke detectors throughout the building and pull stations in the hallways are monitored by a fire alarm system. It reports directly to our dispatch center. Rooms and common areas are covered by an automatic wet pipe sprinkler system.

Fire Drill: 1 on 08/29/2012



# NMSU Fire Department



---

## II. Fire Statistics—2012 Digital Fire log

09/20/2012 Garcia Hall – 1715 International Mall, Time: 02:09 A.M.

Trash can fire in the men's restroom in the lobby. Property loss: \$0.00 no injury or death.  
Cause: Intentional.

06/17/2012 Cervantes Village- 3650 Research, Time: 08:40 A.M.

Electrical indoor grill caught fire on the counter top in the kitchen while cooking. The fire was extinguished by fire personnel. Property loss: less than \$150.00, no injury or death.  
Cause: unintentional.

01/24/2012 Chi Omega- 1700 E University Ave. Time: 8:38 A.M.

A shirt left on a heater caught fire and set off the fire alarm. The fire burned itself out prior to the arrival of fire crews. Property loss: none, no injury or death. Cause: unintentional.

---

## III. Excerpts from NEW MEXICO STATE UNIVERSITY FIRE PREVENTION GUIDELINES AND PRACTICES

Found online at: <http://www.fire.nmsu.edu/FirePrevGuidelines.pdf>

---

## IV. Emergency Action Plan Housing and Residential Life

Found online at:

[http://www.nmsu.edu/Adm\\_Reg\\_Finan/housing/public\\_html/general/security.html](http://www.nmsu.edu/Adm_Reg_Finan/housing/public_html/general/security.html)

---

## V. 2012 Annual Security Report, New Mexico State University Police Department

---



# NMSU Fire Department



New Mexico State University Fire Department offers free Fire Extinguisher Training. To sign up for a class, go to Training Central: <https://trainingcentral.nmsu.edu/>.