



# 2013 Annual Fire Safety Report

## Clery Act Requirement

New Mexico State University  
Fire Safety Reporting [18] HEOA  
Reporting Date: January 1, 2013 to December 31, 2013

---

*NOTE: All fire drills reported below are supervised and have mandatory evacuation for all individuals. During the fire drills there is an inspection of: audio sound, synchronization of light strobes, exit doors, and other factors of the system in place.*

---

### **I. On-campus student housing facilities, description of the facilities and description of fire safety system.**

#### **Residence Halls**

##### **Garcia Hall**

Garcia Hall is a three story fire resistive building with four patios. Dorm rooms encircle the patios.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system.

- Fire Drill: 1 on 09/03/2013

One fire reported, information on section **II Fire Statistics**.

##### **Piñon Hall**

Piñon Hall is a three story wood frame structure. The building is two separate sections connected by a common area. Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system.

- Fire Drill: 1 on 09/04/2013



## **Rhodes-Garrett-Hamiel (RGH)**

RGH is a three story fire resistive building with traditional dorm rooms off the main hallway.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. Hallways and corridors are protected by with an automatic wet pipe sprinkler system.

- Fire Drill: 1 on 09/05/2013

## **Campus Apartments**

### **Cervantes Village**

Cervantes Village are multiple single story wood frame buildings, they contain one, two, and four bedroom apartments.

Fire Protection: The rooms contain individual smoke detectors and CO alarm detectors.

One fire reported, information on section [II Fire Statistics](#).

### **Chamisa Village I & II**

Chamisa Village is a complex made-up of three story wood frame buildings. Apartments come in two and four bedroom layouts.

Fire Protection: Apartments contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system.

#### **Chamisa Village I**

- Fire Drills: 1 on 09/03/2013

#### **Chamisa Village II**

- Fire Drills: 1 on 09/05/2013



### **Vista Del Monte**

Vista Del Monte is a complex made up of two story wood frame buildings. Apartments are in two-bedroom configuration.

Fire Protection: Apartments contain individual smoke detectors and CO detectors.

### **Family Housing**

#### **Tom Fort and Sutherland Villages**

Tom Fort and Sutherland are single-family, single story fire resistive homes.

Fire Protection: The homes contain individual smoke detectors and CO detectors.

#### **Cole Village**

Cole Village are two story fire resistive town houses, they are two bedrooms configuration.

Fire Protection: Each home contains individual smoke detectors and CO detectors.

### **Greek Housing**

#### **Greek & ROTC West (Buildings 100-400)**

Greek Complex West is made up of four sections. They are single story fire resistive dormitory buildings.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations are monitored by a fire alarm system. It reports directly to our dispatch center.

- Fire Drill at Greek 100: 1 on 09/03/2013
- Fire Drill at Greek 200: 1 on 09/03/2013
- Fire Drill at Greek 300: 1 on 09/03/2013
- Fire Drill at Greek 400: 1 on 09/03/2013



### **Greek Complex East (Buildings 500-800)**

Greek Complex East is made up of four, two story wood frame building, each section contains four bedrooms.

Fire Protection: Pull stations and smoke detectors in the hallways, they are monitored by a fire alarm system. The system reports directly to our dispatch center. Each individual bedroom has a smoke detector in place; they are not on the fire alarm reporting system.

- Fire Drill at Greek 500: 1 on 09/04/2013
- Fire Drill at Greek 600: 1 on 09/04/2013
- Fire Drill at Greek 700: 1 on 09/04/2013
- Fire Drill at Greek 800: 1 on 09/04/2013

### **Chi Omega**

Chi Omega is a residential sorority, two story wood frame home.

Fire Protection: Bedrooms contain individual smoke detectors. Smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. A fire sprinkler system is currently under construction and review at Chi Omega.

- Fire Drill: 1 on 09/05/2013

### **Delta Zeta**

Delta Zeta is a residential sorority, single story wood frame home.

Dorm rooms contain individual smoke detectors. Smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatched center.

- Fire Drill: 1 on 01/24/2013
- Fire Drill: 1 on 09/05/2013



## Zeta Tau Alpha

Zeta Tau Alpha is a residential sorority, two story wood frame home.

Fire Protection: Smoke detectors throughout the building and pull stations in the hallways are monitored by a fire alarm system. It reports directly to our dispatch center. Rooms and common areas are covered by an automatic wet pipe sprinkler system.

- Fire Drill: 1 on 01/24/2013
- Fire Drill: 1 on 09/05/2013

## II. Fire Statistics—2013 Digital Fire log

DATE	ADDRESS	INCIDENT
1/29/2013	401 W. Union Ave	Brush Fire
2/9/2013	3650 Research Dr.	Trash or rubbish fire, contained.
2/20/2013	945 College Dr.	Dumpster fire
3/1/2013	1810 E. University Ave.	Outside fire, contained.
3/30/2013	1040 S. Horseshoe	Building fire - A class room and contents fire with smoldering conditions were found by first arriving Engine 301. Mutual aid was called for from City of Las Cruces Fire Department. Fire was extinguished by 5:51 A.M. Property loss: \$1.2 million with no injury or death. Cause: Unintentional.
4/8/2013	Wells St. / Locust St.	Brush Fire
4/8/2013	S. Espina St. / N. Horseshoe	Brush Fire
4/13/2013	1022 Wooten Dr.	Cooking fire, confined to container
4/14/2013	414 McArthur Dr.	Brush fire
5/1/2013	1025 Wooten Dr.	Building fire- A room and contents fire with full fire conditions at a single resident housing were found by first arriving Engine 301. Fire was extinguished by 5:51 P.M. Property loss: approximately \$40,000 with no injury or death. Cause: Intentional, children playing with matches.
5/8/2013	1600 International Mall	Outside rubbish, waste, or trash fire
5/15/2013	3024 Andrew Wall Pl.	Natural vegetation fire.
5/25/2013	Knox St. / Stewart St.	Fire, other (This series of small fires were caused by smoldering twine that was thrown by a hay shredder into hay accidentally by a farm worker.)
5/25/2013	Knox St.	Fire, other
5/26/2013	Knox St.	Fire, other
5/26/2013	Knox St.	Fire, other



DATE	ADDRESS	INCIDENT
5/28/2013	Knox St.	Fire, other
5/29/2013	Knox St. / Gregg St.	Fire, other
9/4/2013	1290 Frenger Mall	Trash or rubbish fire, contained.
9/13/2013	725 Standley Dr.	Passenger vehicle fire
9/19/2013	1420 Frenger Mall	Cooking fire, confined to container
10/2/2013	1530 Wells St.	Building fire - A small smoldering fire in the wall near the door of the conference room was found by first arriving Engine 301. Fire was extinguished on arrival with a portable extinguisher. Property loss: less than \$200.00 with no injury or death. Cause: Unintentional, plumber who was sweating a pipe and caught the insulation on fire.
10/4/2013	1050 Stewart St.	Outside rubbish, waste, or trash fire
10/14/2013	401 W. Union Ave	Outside storage fire
10/19/2013	1735 Stewart St.	Passenger vehicle fire

### III. New Mexico State University Fire Prevention Guidelines and Practices

Found online at: <http://bit.ly/1DyPcMX>

### IV. 2013 Annual Security Report, New Mexico State University Police Department

Found online at: <http://www.nmsupolice.com/files/2013/11/2013SSBulletinR.pdf>

New Mexico State University Fire Department offers free Portable Fire Extinguisher Training. To sign up for a class, go to Training Central: <https://trainingcentral.nmsu.edu/>.