



NMSU Fire Department



2014 Annual Fire Safety Report

Clery Act Requirement

New Mexico State University
Fire Safety Reporting [18] HEOA
Reporting Date: January 1, 2014 to December 31, 2014

NOTE: All fire drills reported below are supervised and have mandatory evacuation for all individuals. During the fire drills there is an inspection of: audio sound, synchronization of light strobes, exit doors, and other factors of the system in place.

I. On-campus student housing facilities, description of the facilities and description of fire safety system.

Residence Halls

Garcia Hall (1715 International Mall)

Garcia Hall is a three story fire resistive building with four patios. Dorm rooms encircle the patios.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system.

- Fire Drill: 1 on 01/22/2014
- Fire Drill: 1 on 09/09/2014

One fire reported. Information is in section **II Fire Statistics**.

One fire not reported to NMSU FD. Information is in section **I Arson Fires**.

Piñon Hall

Piñon Hall is a three story wood frame structure. The building is two separate sections connected by a common area. Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system.

- Fire Drill: 1 on 01/22/2014
- Fire Drill: 1 on 09/09/2014



NMSU Fire Department



Rhodes-Garrett-Hamiel (RGH)

RGH is a three story fire resistive building with traditional dorm rooms off the main hallway.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. Hallways and corridors are protected by with an automatic wet pipe sprinkler system.

- Fire Drill: 1 on 01/22/2014
- Fire Drill: 1 on 09/09/2014

Campus Apartments

Cervantes Village

Cervantes Village are multiple single story wood frame buildings, they contain one, two, and four bedroom apartments.

Fire Protection: The rooms contain individual smoke detectors and CO alarm detectors.

Chamisa Village I & II

Chamisa Village is a complex made-up of three story wood frame buildings. Apartments come in two and four bedroom layouts.

Fire Protection: Apartments contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system.

Chamisa Village I

- Fire Drill: 1 on 01/23/2014
- Fire Drill: 1 on 09/10/2014

Chamisa Village II

- Fire Drill: 1 on 01/23/2014
- Fire Drill: 1 on 09/10/2014



NMSU Fire Department



Vista Del Monte (3540 Research Dr.)

Vista Del Monte is a complex made up of two story wood frame buildings. Apartments are in two-bedroom configuration.

Fire Protection: Apartments contain individual smoke detectors and CO detectors.

One fire reported. Information is in section [II Fire Statistics](#).

Family Housing

Tom Fort and Sutherland Villages (426 McArthur Dr.)

Tom Fort and Sutherland are single-family, single story fire resistive homes.

Fire Protection: The homes contain individual smoke detectors and CO detectors.

One fire reported. Information is in section [II Fire Statistics](#).

Cole Village (2215 John Loveland Ave.)

Cole Village are two story fire resistive town houses, they are two bedrooms configuration.

Fire Protection: Each home contains individual smoke detectors and CO detectors.

One fire reported. Information is in section [II Fire Statistics](#).

Greek Housing

Greek & ROTC West (Buildings 100-400)

Greek Complex West is made up of four sections. They are single story fire resistive dormitory buildings.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations are monitored by a fire alarm system. It reports directly to our dispatch center.

- Fire Drill: 1 on 01/24/2014
- Fire Drill: 1 on 09/11/2014



NMSU Fire Department



Greek Complex East (Buildings 500-800) (1775 Wells St.)

Greek Complex East is made up of four, two story wood frame building, each section contains four bedrooms.

Fire Protection: Pull stations and smoke detectors in the hallways, they are monitored by a fire alarm system. The system reports directly to our dispatch center. Each individual bedroom has a smoke detector in place; they are not on the fire alarm reporting system.

- Fire Drill: 1 on 01/24/2014
- Fire Drill: 1 on 09/11/2014

One fire reported. Information is in section [II Fire Statistics](#).

Chi Omega

Chi Omega is a residential sorority, two story wood frame home.

Fire Protection: Bedrooms contain individual smoke detectors. Smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. A fire sprinkler system is currently under construction and review at Chi Omega.

- Fire Drill: 1 on 01/24/2014
- Fire Drill: 1 on 09/11/2014

Delta Zeta

Delta Zeta is a residential sorority, single story wood frame home.

Dorm rooms contain individual smoke detectors. Smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatched center.

- Fire Drill: 1 on 01/24/2014
- Fire Drill: 1 on 09/11/2014



NMSU Fire Department



Zeta Tau Alpha

Zeta Tau Alpha is a residential sorority, two story wood frame home.

Fire Protection: Smoke detectors throughout the building and pull stations in the hallways are monitored by a fire alarm system. It reports directly to our dispatch center. Rooms and common areas are covered by an automatic wet pipe sprinkler system.

- Fire Drill: 1 on 01/24/2014
- Fire Drill: 1 on 09/11/2014

Academic Buildings

International Public Policy Building (3014 McFie Cir.)

International Public Policy Building (IPP) is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, and classrooms.

Fire Protection: IPP is equipped with a full addressable fire alarm system and a sprinkler fire suppression system.

One fire reported. Information is in section II [Fire Statistics](#).

Non-Academic Buildings

Facilities and Services Carpentry Shop (3120 Locust St.)

The carpentry shop is a Fire Resistive Non-Combustible building that houses offices, wood working machines, and a tool shop.

Fire Protection: The carpentry shop contains individual smoke detectors. Pull stations are monitored by a fire alarm system. It reports directly to our dispatch center.

One fire reported. Information is in section II [Fire Statistics](#).



NMSU Fire Department



Physical Science Laboratory (1050 Stewart St.)

Physical Science Laboratory is a Fire Resistive Non-Combustible building that houses offices and research areas controlled by partnerships with corporations and government agencies.

Fire Protection: Physical Science Laboratory is equipped with a full addressable fire alarm system and a sprinkler fire suppression system.

One fire reported. Information is in section [II Fire Statistics](#).

Fatality or Casualty Fires

Geothermal Road and Las Alturas Drive

New Mexico State University Fire Department responded to a drainage culvert located on Geothermal Road near Las Alturas Drive where a fire fatality was discovered.

One fire reported. Information is in section [II Fire Statistics](#).

Arson Fires

Garcia Hall (1715 International Mall)

New Mexico State University Police Department responded to damage done to several doors on the second floor of C-Patio in Garcia Hall. Complainant stated that unknown person or persons set several door decorations on the second floor of Patio-C on fire, causing damage to the paint of the doors involved.

One fire not reported to NMSU FD. Information is in section [II Fire Statistics](#).

NMSU Parking Lot #23 (2625 Locust St.)

New Mexico State University Police Department responded to a green mattress cushion on fire near Lot 23. NMSU PD put out fire with water.

One fire not reported to NMSU FD. Information is in section [II Fire Statistics](#).



NMSU Fire Department



Fire Statistics—2014 Digital Fire log

DATE	ADDRESS	INCIDENT
01/14/2014	2215 John Loveland Ave.	NFIRS 113 - Cooking fire, confined to container, unintentional, no injuries; undetermined dollar amount
01/27/2014	Geothermal Dr.	NFIRS 112 - Fires in structure other than in a building, unintentional, 1 fatality
02/19/2014	1715 International Mall	NFIRS 130 - Mobile property (vehicle) fire, other, unintentional, no injuries
02/27/2014	1715 International Mall	08B Arson and Neg Arson \$500 to \$2500. NMSU PD responded, no NMSU FD response
03/28/2014	3014 McFie Cir.	NFIRS 161 - Outside storage fire, unintentional, no injuries
03/31/2014	2915 McFie Cir.	NFIRS 154 - Dumpster or other outside trash receptacle fire, undetermined, no injuries
04/12/2014	1600 International Mall	NFIRS 142 - Brush or brush-and-grass mixture fire, , undetermined, no injuries
05/02/2014	1530 Wells St.	NFIRS 150 - Outside rubbish fire, other, undetermined, no injuries
05/02/2014	2911 McFie Cir.	NFIRS 118 - Trash or rubbish fire, contained, undetermined, no injuries
05/08/2014	College Dr.	NFIRS 143 - Grass fire, undetermined, no injuries
08/27/2014	1775 Wells St.	NFIRS 154 - Dumpster or other outside trash receptacle fire, undetermined, no injuries
09/20/2014	3005 Arrowhead Dr.	NFIRS 118 - Trash or rubbish fire, contained, undetermined, no injuries
10/19/2014	3540 Research Dr.	NFIRS 113 - Cooking fire, confined to container, unintentional, no injuries; undetermined dollar amount
11/01/2014	2625 Locust St.	08AA – Arson under \$250. NMSU PD responded, no NMSU FD response
11/08/2014	3120 Locust St.	NFIRS 118 - Trash or rubbish fire, contained, undetermined, no injuries
12/01/2014	1715 International Mall	NFIRS 100 - Fire, other, intentional, no injuries
12/21/2014	1050 Stewart St.	NFIRS 111 - Building fire, unintentional, no injuries
12/30/2014	426 McArthur Dr.	NFIRS 118 - Trash or rubbish fire, contained, undetermined, no injuries



NMSU Fire Department



II. New Mexico State University Fire Prevention Guidelines and Practices

Found online at: <http://fire.nmsu.edu/fire-prevention-guidelines/>.

III. 2014 Annual Security Report, New Mexico State University Police Department

Found online at: <http://www.nmsupolice.com/files/2015/09/2015SSBulletin-LCDACC.pdf>.

New Mexico State University Fire Department offers free Portable Fire Extinguisher Training. To sign up for a class, go to Training Central: <https://trainingcentral.nmsu.edu/>.