



NMSU Fire Department

2018 Annual Fire Safety Report

Clery Act Requirement



New Mexico State University
Fire Safety Reporting [18] HEOA
Reporting Date: January 1, 2017 to December 31, 2017

NOTE: All fire drills reported below are supervised, meet International Fire Code Chapter 4 Emergency Planning and Preparedness, and have mandatory evacuation for all individuals. During the fire drills there is an inspection of: audio sound, synchronization of light strobes, exit doors, and other factors of the system in place.

I. On-campus student housing facilities, description of the facilities and description of fire safety system.

Residence Halls

Garcia Hall (1715 International Mall)

Garcia Hall is a three-story fire resistive building with four patios. Dorm rooms encircle the patios.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 02/06/2017
- Fire Drill: 1 on 09/12/2017

One fire reported. Information is in section **II Fire Statistics**.

Piñon Hall (1780 East University Avenue)

Piñon Hall is a three-story wood frame structure. The building is two separate sections connected by a common area. Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 02/06/2017



NMSU Fire Department

2018 Annual Fire Safety Report

Clery Act Requirement



- Fire Drill: 1 on 09/12/2017

No fires reported. Information is in section [II Fire Statistics](#).

Rhodes-Garrett-Hamiel (RGH) (2715-2735 Jordan Road)

RGH is a three-story fire resistive building with traditional dorm rooms off the main hallway.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Hallways and corridors are protected by with an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 02/06/2017
- Fire Drill: 1 on 09/11/2017

One fire reported. Information is in section [Arson Fires](#).

Campus Apartments

Cervantes Village

Cervantes Village are multiple single story wood frame buildings, they contain one, two, and four bedroom apartments.

Fire Protection: The rooms contain individual smoke detectors and CO alarm detectors.

No fire reported. Information is in section [II Fire Statistics](#).

Chamisa Village I & II (1735 Stewart Street)

Chamisa Village is a complex made-up of three-story wood frame buildings. Apartments come in two and four bedroom layouts.

Fire Protection: Apartments contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Rooms and main areas are



NMSU Fire Department

2018 Annual Fire Safety Report

Clery Act Requirement



protected by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

Chamisa Village I

- Fire Drill: 1 on 02/07/2017
- Fire Drill: 1 on 09/11/2017

Chamisa Village II

- Fire Drill: 1 on 02/07/2017
- Fire Drill: 1 on 09/11/2017

No fire reported. Information is in section [II Fire Statistics](#).

Vista Del Monte

Vista Del Monte is a complex made up of two story wood frame buildings. Apartments are in two-bedroom configuration.

Fire Protection: Apartments contain individual smoke detectors and CO detectors.

No fires reported. Information is in section [II Fire Statistics](#).

Family Housing

Tom Fort and Sutherland Villages

Tom Fort and Sutherland are single-family, single story fire resistive homes.

Fire Protection: The homes contain individual smoke detectors and CO detectors.

One fire reported. Information is in section [II Fire Statistics](#).



NMSU Fire Department

2018 Annual Fire Safety Report

Clery Act Requirement



Greek Housing

Chi Omega (1700 East University Avenue)

Chi Omega is a residential sorority, two story wood frame home.

Fire Protection: Bedrooms contain individual smoke detectors. Smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Rooms and common areas are covered by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 02/06/2017
- Fire Drill: 1 on 09/12/2017

No fires reported. Information is in section [II Fire Statistics](#).

Delta Zeta (1600 East University Avenue)

Delta Zeta is a residential sorority, single story wood frame home.

Dorm rooms contain individual smoke detectors. Smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Rooms and common areas are covered by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 02/07/2017
- Fire Drill: 1 on 09/12/2017

No fires reported. Information is in section [II Fire Statistics](#).

Zeta Tau Alpha (1699 East University Avenue)

Zeta Tau Alpha is a residential sorority, two story wood frame home.

Fire Protection: Smoke detectors throughout the building and pull stations in the hallways are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Rooms and common areas are covered by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.



NMSU Fire Department

2018 Annual Fire Safety Report

Clery Act Requirement



- Fire Drill: 1 on 02/07/2017
- Fire Drill: 1 on 09/12/2017

No fires reported. Information is in section II [Fire Statistics](#).

Non-Academic Buildings

Fires in Non-Academic Buildings

No fires reported. Information is in section II [Fire Statistics](#).

Academic Buildings

Gardiner Hall (1255 North Horseshoe)

Gardiner Hall is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, laboratories, and classroom areas.

Fire Protection: Gardiner Hall is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill on 09/11/2017

Gerald Thomas Hall (940 E. College Avenue)

Gerald Thomas Hall is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, and classrooms.

Fire Protection: Gerald Thomas Hall is equipped with a full addressable fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center.

- Fire Drill on 09/11/2017



NMSU Fire Department

2018 Annual Fire Safety Report

Clery Act Requirement



Goddard Hall and Annex (1100 South Horseshoe)

Goddard Hall and Annex is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, laboratories, and classroom areas.

Fire Protection: Goddard Hall and Annex is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill on 09/11/2017

Milton Hall (2915 McFie Circle)

Milton Hall is a multi-story Fire Resistive Non-Combustible building that houses offices, conference rooms, classrooms, lecture rooms, laboratories, and work station areas.

Fire Protection: Milton Hall is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill on 09/12/2017

Thomas and Brown Hall (1125 Frenger Mall)

Thomas and Brown Hall is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, laboratories and classroom areas.

Fire Protection: Thomas and Brown Hall is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25. Fire Drill on 09/12/2017

Fires in Academic Buildings

One fire reported at Chemistry Hall, 1175 North Horseshoe. Information is in section II **Fire Statistics**.



NMSU Fire Department

2018 Annual Fire Safety Report

Clery Act Requirement



Fatality or Casualty Fires

None reported.

Arson Fires

None reported or identified.

II. Fire Statistics

2017 Digital Fire Log

FIRES INSIDE STRUCTURES		
DATE	ADDRESS	INCIDENT
09/25/2017	975 Gregg Street (Sutherland Village)	113 - Cooking fire, confined to container
10/20/2017	2725 Jordan Road (Rhodes-Garrett-Hamiel (RGH))	113 - Cooking fire, confined to container
11/07/2017	1175 North Horseshoe (Chemistry Building)	251 - Excessive heat, scorch burns with no ignition
11/08/2017	1715 International Mall (Garcia Hall)	113 - Cooking fire, confined to Container
FIRES OUTSIDE STRUCTURES		
DATE	ADDRESS	INCIDENT
1/29/2017	4525 Observatory Road	150 - Outside rubbish fire, other
3/2/2017	1175 North Horseshoe	151 - Outside rubbish, trash or waste fire
4/25/2017	2902 McFie Circle	143 - Grass fire
5/6/2017	East Union Avenue	151 - Outside rubbish, trash or waste fire
5/15/2017	College Avenue	151 - Outside rubbish, trash or waste fire
5/22/2017	College Avenue	140 - Natural vegetation fire, other
12/2/2017	3005 Arrowhead Drive	154 - Dumpster or other outside trash receptacle fire



NMSU Fire Department

2018 Annual Fire Safety Report

Clery Act Requirement



III. New Mexico State University Fire Prevention Guidelines and Practices

Found online at: <https://fire.nmsu.edu/fire-prevention-guidelines/>

IV. 2017 Annual Security Report, New Mexico State University Police Department

Found online at: <https://www.nmsupolice.com/annual-reports/>

V. 2017 Annual Reports, New Mexico State University Fire Department

Found online at: <https://fire.nmsu.edu/annual-reports/>

New Mexico State University Fire Department offers free Portable Fire Extinguisher Training. To sign up for a class, go to Training Central: <https://trainingcentral.nmsu.edu/>.