



NMSU Fire Department

2019 Annual Fire Safety Report

Clery Act Requirement



New Mexico State University
Fire Safety Reporting [18] HEOA
Reporting Date: January 1, 2018 to December 31, 2018

NOTE: All fire drills reported below are supervised, meet International Fire Code Chapter 4 Emergency Planning and Preparedness, and have mandatory evacuation for all individuals. During the fire drills there is an inspection of: audio sound, synchronization of light strobes, exit doors, and other factors of the system in place.

I. On-campus student housing facilities, description of the facilities and description of fire safety system.

Residence Halls

Garcia Hall (1715 International Mall)

Garcia Hall is a three-story fire resistive building with four patios. Dorm rooms encircle the patios.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 02/12/2018
- Fire Drill: 1 on 09/11/2018

No fires reported. Information is in section **II Fire Statistics**.

Piñon Hall (1780 East University Avenue)

Piñon Hall is a three-story wood frame structure. The building is two separate sections connected by a common area. Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 02/12/2018



NMSU Fire Department

2019 Annual Fire Safety Report

Clery Act Requirement



- Fire Drill: 1 on 09/11/2018

No fires reported. Information is in section [II Fire Statistics](#).

Rhodes-Garrett-Hamiel (RGH) (2715-2735 Jordan Road)

RGH is a three-story fire resistive building with traditional dorm rooms off the main hallway.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Hallways and corridors are protected by with an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 02/18/2018
- Fire Drill: 1 on 09/04/2018

No fires reported. Information is in section [II Fire Statistics](#).

Campus Apartments

Cervantes Village

Cervantes Village are multiple single story wood frame buildings, they contain one, two, and four bedroom apartments.

Fire Protection: The rooms contain individual smoke detectors and CO alarm detectors.

No fire reported. Information is in section [II Fire Statistics](#).

Chamisa Village I & II (1735 Stewart Street)

Chamisa Village is a complex made-up of three-story wood frame buildings. Apartments come in two and four bedroom layouts.

Fire Protection: Apartments contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Rooms and main areas are



NMSU Fire Department

2019 Annual Fire Safety Report

Clery Act Requirement



protected by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

Chamisa Village I

- Fire Drill: 1 on 02/13/2018
- Fire Drill: 1 on 09/13/2018

Chamisa Village II

- Fire Drill: 1 on 02/13/2018
- Fire Drill: 1 on 09/13/2018

No fire reported. Information is in section [II Fire Statistics](#).

Vista Del Monte

Vista Del Monte is a complex made up of two story wood frame buildings. Apartments are in two-bedroom configuration.

Fire Protection: Apartments contain individual smoke detectors and CO detectors.

No fires reported. Information is in section [II Fire Statistics](#).

Family Housing

Tom Fort and Sutherland Villages

Tom Fort and Sutherland are single-family, single story fire resistive homes.

Fire Protection: The homes contain individual smoke detectors and CO detectors.

No fires reported. Information is in section [II Fire Statistics](#).



NMSU Fire Department

2019 Annual Fire Safety Report

Clery Act Requirement



Greek Housing

Chi Omega (1700 East University Avenue)

Chi Omega is a residential sorority, two story wood frame home.

Fire Protection: Bedrooms contain individual smoke detectors. Smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Rooms and common areas are covered by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 02/12/2018
- Fire Drill: 1 on 09/04/2018

No fires reported. Information is in section [II Fire Statistics](#).

Delta Zeta (1600 East University Avenue)

Delta Zeta is a residential sorority, single story wood frame home.

Dorm rooms contain individual smoke detectors. Smoke alarms in the common areas are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Rooms and common areas are covered by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 02/12/2018
- Fire Drill: 1 on 09/04/2018

No fires reported. Information is in section [II Fire Statistics](#).

Zeta Tau Alpha (1699 East University Avenue)

Zeta Tau Alpha is a residential sorority, two story wood frame home.

Fire Protection: Smoke detectors throughout the building and pull stations in the hallways are monitored by a fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. Rooms and common areas are covered by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.



NMSU Fire Department

2019 Annual Fire Safety Report

Clery Act Requirement



- Fire Drill: 1 on 02/12/2018
- Fire Drill: 1 on 09/04/2018

No fires reported. Information is in section II [Fire Statistics](#).

Non-Academic Buildings

Fires in Non-Academic Buildings

One fire reported at Frenger Food Court, 1420 Frenger Mall. Information is in section II [Fire Statistics](#).

One fire reported at Corbett Center – Taos Cafeteria, 1600 International Mall. Information is in section II [Fire Statistics](#).

Academic Buildings

Spring 2018

Astronomy Building (1320 Frenger Mall)

Astronomy Building is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, laboratories, and classroom areas.

Fire Protection: Astronomy Building is equipped with a full addressable fire alarm system The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center.

- Fire Drill on 02/13/2018

Breland Hall (1525 Stewart Street)

Breland Hall is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, and classrooms.

Fire Protection: Breland Hall is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to



NMSU Fire Department

2019 Annual Fire Safety Report

Clery Act Requirement



NFPA 72 and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill on 02/13/2018

Guthrie Hall (1325 International Mall)

Guthrie Hall is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, and classroom areas.

Fire Protection: Guthrie Hall is equipped with a full addressable fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center.

- Fire Drill on 02/13/2018

Walden Hall (1200 Frenger Mall)

Walden Hall is a multi-story Fire Resistive Non-Combustible building that houses offices, conference rooms, classrooms, lecture rooms, and work station areas.

Fire Protection: Walden Hall is equipped with a full addressable fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center.

- Fire Drill on 02/13/2018

Young Hall (1300 South Horseshoe)

Young Hall is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, laboratories and classroom areas.

Fire Protection: Young Hall is equipped with a full addressable fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center.

- Fire Drill on 02/12/2018



NMSU Fire Department

2019 Annual Fire Safety Report

Clery Act Requirement



Fall 2018

Center for the Performing Arts (1000 East University Avenue)

Center for the Performing Arts is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, laboratories, and classroom areas.

Fire Protection: Center for the Performing Arts is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system and fire pump. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. The fire sprinkler system and fire pump are inspected quarterly and maintained to NFPA 25.

- Fire Drill on 09/04/2018

Chemistry Complex (1175 North Horseshoe)

Chemistry Complex is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, and classrooms.

Fire Protection: Chemistry Complex is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill on 09/10/2018

Foster Hall (1200 South Horseshoe)

Foster Hall is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, laboratories and classroom areas.

Fire Protection: Foster Hall is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill on 09/10/2018

Music Hall (1075 North Horseshoe)



NMSU Fire Department

2019 Annual Fire Safety Report

Clery Act Requirement



Music Hall is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, laboratories, and classroom areas.

Fire Protection: Music Hall is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill on 09/04/2018

Stan Fulton Athletic Center (1815 Wells Street)

Stan Fulton Athletic Center is a multi-story Fire Resistive Non-Combustible building that houses offices, conference rooms, classrooms, lecture rooms, laboratories, and work station areas.

Fire Protection: Stan Fulton Athletic Center is equipped with a full addressable fire alarm system. The fire alarm system is inspected/tested annually and maintained to NFPA 72 and it reports directly to NMSU PD dispatch center.

- Fire Drill on 09/10/2018

Fires in Academic Buildings

One fire reported at O'Donnell Hall, 1220 Stewart Street. Information is in section [II Fire Statistics](#).

Fatality or Casualty Fires

None reported.

Arson Fires

None reported or identified.



NMSU Fire Department

2019 Annual Fire Safety Report

Clery Act Requirement



II. Fire Statistics

2018 Digital Fire Log

FIRES INSIDE STRUCTURES

DATE	ADDRESS	INCIDENT
03/01/2018	1220 Stewart Street (O'Donnel Hall)	251 - Excessive heat, scorch burns with no ignition
08/20/2018	1420 Frenger Mall (Frenger Food Court)	113 - Cooking fire, confined to container
10/24/2018	1600 International Mall (Corbett Center – Taos Cafeteria)	113 - Cooking fire, confined to container

FIRES OUTSIDE STRUCTURES

DATE	ADDRESS	INCIDENT
04/03/2018	1715 International Mall	140 - Natural vegetation fire, other
04/11/2018	3165 Williams Avenue	140 - Natural vegetation fire, other
05/03/2018	3030 Breland Drive	131 - Passenger vehicle fire
05/16/2018	Stewart Street and Union Intersection	142 - Brush or brush-and-grass mixture fire
11/13/2018	1775 Stewart Street	131 - Passenger vehicle fire
12/23/2018	4530 Observatory Road	151 - Outside rubbish, trash or waste fire



NMSU Fire Department

2019 Annual Fire Safety Report

Clery Act Requirement



III. New Mexico State University Fire Prevention Guidelines and Practices

Found online at: <https://fire.nmsu.edu/fire-prevention-guidelines/>

IV. 2018 Annual Security Report, New Mexico State University Police Department

Found online at: <https://www.nmsupolice.com/annual-reports/>

V. 2018 Annual Reports, New Mexico State University Fire Department

Found online at: <https://fire.nmsu.edu/annual-reports/>

New Mexico State University Fire Department offers free Portable Fire Extinguisher Training. To sign up for a class, go to Training Central: <https://trainingcentral.nmsu.edu/>.